



The Westgate School Accessibility Plan (Reviewed September (2021))

Access audit

Feature For example:	Description	Actions to be taken	Person responsible	Date to complete actions by
Number of storeys	Ground and first floor across the majority of the site. Single-storey block in English.	N/A		
Corridor access	Most corridors are wide enough to allow safe passage of physically impaired pupils provided they leave lessons 5-10 minutes early.	None required		
Lifts	There are 3 lifts across the school site in PE, Science and near the Learning Resource Centre. There are also 2 additional disabled specific lifts for additional access.	None required		
Parking bays	The school has 96 parking bays, 4 of which are designated disabled bays and 8 visitor bays.	None required		
Entrances	There are 3 minor entrances which are all accessible.	None required		
Ramps	There are ramps at main and minor entrances. All other entrances are level.	None required		
Toilets	There are 75 toilets on the premises and 14 of these are disabled toilets.	None required		
Reception area	Reception is fully accessible for guests, students and staff.	None required		

Internal signage	Internal signage is consistent, visible for those with visual or physical impairments and to support students they have a thorough induction process and assistance is provided to visitors and PI students.	None required		
Emergency escape routes	Students, staff and visitors are made aware of emergency escape routes and procedures should evacuation be necessary.	None required		

Approved by:

Date:

Next review date: September 2024